

North Star Auto Service

Where Customers Send Their Friends

ESTIMATE

Bill To Dr. Sarah Campbell
Suite 432
774 Burrard Street
Vancouver, B.C. V5Y 6U6
Canada
Phone (604) 555-1212 Ext 44
Invoice Date 28 Sep 2003

Vehicle SARA1
Desc Silver 2003
Make Jaguar Vanden Plas Sedan
Engine V8-3996 4.0L DOHC
Odometer 24,435
VIN

Invoice Date 28 Sep 2003
Appointment 28 Sep 2003 11:10 am
Promised 29 Sep 2003 6:00 pm

Work Order # 000000980
Invoice # N/A
Svc Advisor Sheardown, Ralph
Technician McFarlane, Todd

Estimated Work

Water Pump - Replace

Includes Removal and Replacement of Water Pump. Includes removal of required equipment for access. Includes refilling coolant level, testing freeze point and PH Acid Level.

Technical Service Rate				\$204.72	GP
Water Pump Assembly	1.00	Units		\$150.00	GP
Radiator Hose	4.00	Units	\$3.99 / Unit	\$15.96	GP
Engine coolant	1.00	Units		\$2.49	GP

Reminder

Cooling System should be flushed every 2 years or 50,000 km.

Sub \$373.17

Estimated Total

Total Labor				\$204.72	
Total Parts				\$168.45	
Total Before Taxes & Miscellaneous Charges				\$373.17	
(*) Shop Supplies				\$18.66	GP
(G) Canadian Goods and Services Tax (GST)			7 %	\$27.43	
(P) British Columbia Provincial Sales Tax			7.5 %	\$29.39	
Totals				\$448.65	

This estimate for parts and labour is valid for 30 days. Prices listed are for estimated costs to perform the repairs as listed, following a visual inspection of the vehicle system. Upon disassembly of components, additional parts or repairs may be identified as needing replacement, and maybe subject to additional costs.